

CHAL 0963-60

Copy 4 of 4

MEMORANDUM FOR: Acting Chief, DPD

SUBJECT: Reassessment of U-2/U-2C Requirements

1. Since the occurrence of the crashes of Articles #349 and #360, several possibilities have been considered concerning repair of #349 and reconfiguring additional U-2's to U-2C type.

2. The following are Operations recommendations concerning #349, additional U-2C requirements, and assignment of all Project U-2/U-2C assets:

a. It is recommended that Article #349 be repaired and retained as U-2 type.

b. It is recommended that two additional U-2's be modified to U-2C configuration.

c. If the above recommendations are approved aircraft assignment would be:

- (1) Detachment B:
- (2) Detachment C:
- (3) Edwards:



25X1A

STANLEY W. BEERLI

Colonel USAF

Chief, Operations Branch, DPD-DD/P



ILLEGIB

Acting Chief, DPD-DD/P

DPD/OPS/CHAL [REDACTED] (4 May 1960)

25X1A

Distribution:

- Copy 1 - DPD/COPS
- Copy 2 - AC/DPD
- Copy 3 - DPD/OPS/CHAL
- ✓ Copy 4 - DPD/RI

ILLEGIB

